

Price List Mammut Repair & Care (EN) *Excludes Shipping Cost

MAMMUT



Product Detail	£ - Prices exclude VAT
Zipper puller replacement	£0.00
Zipper slider pocket replacement	£12.75
Zipper slider front replacement	£17.00
Zipper slider front/sides	£76.50
Zipper replacement pockets (non waterproof)	£42.50
Zipper replacement pockets (waterproof)	£59.50
Glue + stitch zip pocket fasteners on both sides	£25.50
Seam stich repair	£8.50
Seam stich repair + tape	£21.25
Shorten sleeves	£38.25
Shorten sleeves with elasticated band	£51.00
Shorten sleeves with cuffs	£76.50
Shorten sleeves with elbow seam	£76.50
Replace Velcro fastener	£34.00
Repair lining with patch	£21.25
Repair lining with fabric strip	£38.25
Replace snap button	£8.50
Remove pilling	£0.00
Cover the chamber with fabric from down jacket	£38.25
Patch hole/tear	£21.25
Insert fabric strip hole/tear	£38.25

Zipper slider pocket replacement	
Zipper replacement	

1.1 1 A A

Zipper puller replacement

Product Detail

Pants





£0.00	
20100	

£12.75

£ - Prices exclude VAT

£59.50

Zipper replacement pockets (non waterproof)	£42.50
Zipper replacement pockets (waterproof)	£59.50
Zipper replacement (Ventilation on the leg) short	£51.00
Zipper replacement (Ventilation on the leg) long	£76.50
Shorten	£42.50
Shorten with cuffs	£51.00
Shorten with drawstring or lining	£59.50
Shorten with snow guard	£76.50
Shorten with zip	£76.50
Shorten with zip and snow guard	£114.75
Shorten with seam at the knee incl. taping	£93.50
Shorten with seam at the knee + lining incl. taping	£114.75
Shorten with seam at the knee + long zip incl. taping	£136.00
Seam stich repair	£8.50
Seam stich repair + tape	£21.25
Sew + tape new edge protection around for ski trouser	£114.75
Replace snap button	£8.50
Remove pilling	£0.00
Patch hole/tear	£21.25
locart fabric atrip bala /toar	C20 25

£38.25

Insert fabric strip hole/tear



Sleeping bags

Product Detail	£ - Prices exclude VAT
Patch hole/tear	£21.25
Insert fabric strip hole/tear	£38.25
Zipper slider replacement	£21.25
Zipper replacement front/sides	£114.75
Replace drawcord	£34.00
Replace velcro fastener	£34.00

MAMMUT





Product Detail

£ - Prices exclude VAT

Patch hole/tear	£21.25
Correct seam	£8.50
Replace buckle	£12.75







Product Detail	£ - Prices exclude VAT
Re-gluing / sewing soles or open seams	£17.00
Sole replacement	£76.50 - £153.00
Eyelets and hook replacement	£17.00
Tear / hole lining repair (only leather shoes)	£42.50
Light Stitch Repair/Patch	£15.00

MAMMUT

Hardware



Product Detail	£ - Prices exclude VAT
Zipper puller replacement	£0.00
Zipper slider replacement	£12.75
Patch hole/tear	£21.25
Insert fabric strip hole/tear	£38.25
Repair inner lining with patch	£21.25
Repair inner lining with fabric strip	£38.25
Zipper replacement	£76.50
Buckle repair	£12.75
Strap repair	£25.50






Product Detail	£ - Prices exclude VAT
Barryvox Service (Update incl.)	£17.00
Barryvox Service + Update Pulse	£22.10
Barryvox Carrying system	£25.50







Product Detail	£ - Prices exclude VAT
Full Check	£51.00
Folding the airbag	£25.50